

Form 9-331
Dec. 1973

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other Water Injection

2. NAME OF OPERATOR
BURNETT OIL CO., INC.

3. ADDRESS OF OPERATOR 76102
1214 First Nat'l. Bank Bldg., Ft. Worth, Texas

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' from south and east lines of
AT TOP PROD. INTERVAL: Sec. 1-17S-30E.
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Perform Remedial Work.		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-5/8" 24# casing is cemented from 529' to surface. 4 1/2" 9.5# casing is cemented from 3223' to 1337'. In the recent bradenhead survey, a small amount of fluid at low pressure was trickling out bradenhead. On July 21, 1983, Mr. Mike Williams gave verbal approval for the following remedial work:

Squeeze 50 sacks class "C" cement + 70 sacks Halliburton light cement down between 8-5/8" and 4 1/2" casing. This calculated to be 150% of theoretical fill.

Mr. Peter Chester with BLM gave verbal approval on August 2, 1983.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter Chester TITLE Consultant DATE August 2, 1983

APPROVED BY (This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

AUG 27 1983

NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

Form Approved.

Budget Bureau No. 42-R1424

5. LEASE
NM-2747

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jackson "B"

9. WELL NO.
32

10. FIELD OR WILDCAT NAME
Square Lake

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 1-17S-30E

12. COUNTY OR PARISH Eddy 13. STATE New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

c/27

