

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
TENNECO OIL COMPANY
3. ADDRESS OF OPERATOR
6800 Park Ten Blvd., San Antonio, TX. 78213
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1010' FNL + 1710' FWL (NE NW)
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

☐
☐
☐
☐
☐
☐
☐
☐

(other) SET INTERMEDIATE STRING.

RECEIVED

OCT 16 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set 65 JTS 8 5/8" 32# New K 55 ST&C @ 2800' W/200 Class C + Thixament, +
2% CaCl₂ + 10% GEL + 1/4 #/ SX Floceze, 800 Sx 4 + 10 #/SX-Salt + 6# GEL/SX
+ 1/4 #/SX Floceze, Tailed in W/200 S x S "C" + 2% CaCl₂, to surface, tested
W/1500 PSI

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED F. R. Bell TITLE STAFF PRODUCTION ANALYST DATE 10-10-79

(This space for Federal or State office use)

APPROVED BY (Cdy. Sgd.) GEORGE H. STEWART TITLE ACTING DISTRICT ENGINEER DATE 10/10/79
CONDITIONS OF APPROVAL, IF ANY:

