Form 9-331 Dec. 1973

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GFOLOGICAL SURVEY

ONITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 074936
GEOLOGICAL SURVEY RECEIVED	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plugbabe to a diffe or reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🗑 OCD	Mc Intyre Federal
well Well other	9. WELL NO. 8
2. NAME OF OPERATOR ARCO Oil & Gas Company	
Division of Atlantic Richileta Company	L. T. M. TELS ON THE SOME TO MILE
3. ADDRESS OF OPERATOR	Eded MILIB Hered
P. O. Box 1/10, Hobbs, New Mexico 88240	11. SEC., I., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) 1650' FSL & 1980' FWL Unit Letter "K" AT SURFACE:	17-17S-30E 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	
AT TOTAL DEPTH: As above	Eddy
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. W. HO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3660.1' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	(NOTE: Report consists of single
ABANDON*	AUG 1 1 1980
(other) Spud run conductor pi	U.S. GEULUGICAL SURVEY
surf csg & cmt. 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined.	irectionally drilled, give substitute in the interest of the i
On 7-29-80 ran 38' of 30" conductor pipe. Cmtd hole @ 1:00 PM 7-31-80. Drld to 450'. RIH w/Cmtd w/ 425 sx C1 "C" cmt w/ 2% CaCl. Circ 38 tested csg to 1000# for 30 mins, OK. Volume of w/ 2% CaCl. Circ 50 cut ft cmt to surf. ApproxEstimated minimum formation temperature in zone strength @ time of test was 1200 PSIG. Actual csg was 11 hrs.	13-3/8" OD K-55 54.5# csg set @ 446'. sx cmt to surf. WOC 11 hrs. Pressure cmt slurry was 561 cu ft of C1 "C" cmt ximate cmt slurry when mixed was 79°. of interest was 67°. Estimate of cmt
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
SIGNED TITLE Dist. Drlg.	0.16.19.0
SIGNED WITH TITLE DIST. Drig.	DUPL. DATE 0/0/00

(This space for Federal or State office use)

__ DATE _

ACCEPTED FOR RECORD

__ TITLE _

AUG 131980

U.S. GECLOGICAL SURVEY ROSWELL, NEW MEXICO

*See Instructions on Reverse Side