

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NM OIL & GAS COMMISSION
Artesia, NM 88210

Form approved
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different zone or soil.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER	JAN 4 1982	7. LEASE DESIGNATION AND SERIAL NO. NM-14847
2. NAME OF OPERATOR General American Oil Company of Texas	O. C. D.	8. IF INDIAN, ALIOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 128 Loco Hills, New Mexico 88255	ARTESIA, OFFICE	9. WELL NO. 12
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FSL and 2310' FEL		10. FIELD AND POOL, OR WILDCAT South Empire Morrow
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3671.1' KB	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T-17S, R-29E
		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*		
REPAIR WELL	CHANGE PLANS	(Other)	Production Casing	X	
(Other)			(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-26-81 Ran 267 joints of 5-1/2" 17# and 15.5#, N-80 and K-55, LT&C, 8rd. casing and set @ 10,740' (T.D.).

12-27-81 Cemented 5-1/2" casing with lead slurry of 200 sacks BJ-Lite with 5# salt, 5# gilsonite, 1/4# cello-flake, 5/10% D-31 and 2/10% R-6; followed by tail slurry of 1100 sacks Class "H" cement with 5# salt, 6/10% D-19, 3/10% D-31, 2/10% R-6. Bump plug @ 2750# — float held ok. Full circulation during cement operations.

DEC 30 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]
ACCEPTED FOR RECORD
(This space for Federal or State CHAPMAN)

TITLE Engineer

DATE December 29, 1981

APPROVED BY [Signature]
CONDITIONS OF APPLICABILITY

TITLE

DATE

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

