

N.M.O.C.D. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)Form approved.
Budget Bureau No. 42 R1424
5. LEASE DESIGNATION AND SERIAL NO.

NM-14847

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Green "B"

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

South Empire Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 7, T-17S, R-29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL ☐ GAS ☒ OTHER ☐

2. NAME OF OPERATOR

General American Oil Company of Texas

3. ADDRESS OF OPERATOR

P. O. Box 128 Loco Hills, New Mexico 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

2080' FEL and 1780' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3670.8' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOT OR ACIDIZE ☐ABANDON* ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐Surface Casing ☒(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Well was spud on April 29, 1981 at 8:00 P.M.

2. 13-3/8" 54.5# K-55 was run to 318' on April 30, 1981 and cemented as follows:

- Volume of cement: 500 sacks Class "C" cement with 2% calcium chloride.
- Brand of cement: Southwestern Portland.
- Slurry temperature: 60° F (approximate).
- Formation temperature: 68° F (approximate).
- Full circulation during cement operations.
- 100 sacks cement returned to surface.
- Waited on cement for 21 hours.
- Tested B.O.P.E. to 600# for 30 minutes.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Engineer

DATE May 1, 1981

(This space for Federal or State office use)

ACCEPTED FOR RECORD
ROGER A. CHAPMAN

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 5 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side