RECEIVED LY O. C. D. Dec. 1973 ARTESIA, OFF

.

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES	5. LEASE NM-013814
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SORVET	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other	Evans Fed Com 9. WELL NO.
well well other 2. NAME OF OPERATOR	1
Santa Fe Energy Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Wildcat
500 W. Illinois, Suite 500, Midland, TX 79701 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
helow.)	Sec 6, T-17S, E-30E
AT SURFACE: 1980' FNL, 870' FEL, Sec 6, T-17S, AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Eddy New Mexico
AT TOTAL DEPTH:	14. API NO. NA
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3687.6 GR
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
Set 85 sx plug @ 10,300-10,100' RR 12	directionally drilled, give subsurface locations and not to this work.)* 5, from Bob Pitishy to plug drill pipe below & between all Plugs set as below: 55 sx @ 100+ - surface 2:00 noon 1/6/85. Cleaned pit. site not conditioned for inspection. 65 sx @ 6350-6200' Post FD-2 4-5-85
Cut 9 5/8" wellhead off.	MA
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED Billie Hood TITLE Sr. Prod. Clerk DATE 12-23-84	
(Thus space for Federal or State office use)	
APPROVED BY SOLD WAS A STATE OF APPROVAL IF ANY	