

11. Surface Ownership:

Surface Lessee:

Bogle Farms
1206 Pecan
Artesia, NM 88210
Attn: Lewis Derrick

Mineral Ownership:

Bureau of Land Management
P. O. Box 1778
Carlsbad, NM 88220

12. Other Information:

- A. Topography: Stabilized and Coppice sand dunes or mesquite anchored hummocks covered with shin oak, mesquite, yucca, broom snakeweed and various grasses. Ground level elevation at the wellsite is 3625'.
- B. Soil: Loamy sands with inclusions of chert and quartzite gravel.
- C. Ponds and Streams: There are no rivers, streams, lakes or major ponds in the area. Bear Grass Draw is located approximately 2 miles west.
- D. Archeological Survey: An archaeological survey was performed by Pecos Archeological Consultants on February 3, 1990. No cultural sites were recorded. The survey report is included as Exhibit 5.
- E. Land Use: Grazing

13. Compliance:

The company representatives responsible for assuring compliance with the approved Surface Use and Operations Plan are as follows:

Steve Limke
(915) 688-0494 (Office)
(915) 684-9791 (Home)
Midland, Texas

Rick Sievert
(915) 688-0448 (Office)
(915) 682-6068 (Home)
Midland, Texas