

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
811 South First, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO. 30-015-27108
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-255
7. Lease Name or Unit Agreement Name Muskegon 16 State Com
8. Well No. 1
9. Pool name or Wildcat SWD; Cisco
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3577

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> <input checked="" type="checkbox"/> OTHER SWD	2. Name of Operator Mack Energy Corporation
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 16 Township 17S Range 29E NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>


SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/21/2000 RU Pick up on tbg & overshot was not jayed on pkr. Tried to unset pkr & couldn't. POH & found holes in 2nd jt & 3rd jt off bottom. RIH w/new overshot & jay on to pkr and pull out of hole. POH & lay down Plastic coated tbg.

2/22/2000 RIH w/new 5 1/2" Trump pkr w/on off tool & 297 joints new plastic coated tbg. Set pkr @ 8862' & jay off pkr. Pump 145 bbls pkr fluid & jay back on to pkr. Pull 18,000 tension & test csg. 300# 30 min.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Analyst DATE 3/30/00

TYPE OR PRINT NAME Crissa D. Carter TELEPHONE NO. (505)748-1288

(This space for State Use)

APPROVED BY more Stillwell TITLE Field Rep. # DATE 4/11/2000

CONDITIONS OF APPROVAL, IF ANY: