Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Revised 1-1-89	Form C-103 C Revised 1-1-89	15#1 Nn
----------------	--------------------------------	------------

DISTI	RICI	u			
PO.F	l rof	980.	Hobbir	NM	88240

OH CONCEDUATION DIVISION

WELL API NO.	1
30-015-28487	
5. Indicate Type of Lease	
STATE	FEE
6. State Oil & Gas Lease No.	

	P.O. Box 2088		WELL API NO.	
	1,0,000,2000		30-015-28487	
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE FEE	
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			6. State Oil & Gas Lease No. LG-5665	
CUNDOW NOTICES AND DEPORT	CON WELLS			
SUNDRY NOTICES AND REPORT (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF DIFFERENT RESERVOIR. USE "APPLICA" (FORM C-101) FOR SUCH PROP	TO DEEPEN OR P TON FOR PERMIT	LUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: Off. GAS WELL WELL [X] OTH	ER .		Cedro APG State Com	
2. Name of Operator			8. Well No.	
YATES PETROLEUM CORPORATION /			1	
3. Address of Operator 105 South Fourth Street - Artesia, N	M 88210	· · ·	9. Pool name or Wildcat Cedar Lake Morrow	
4. Well Location		•		
Unit Letter C : 660 Feet From The	North	Line and 22	30 Feet From The West Line	
Section 36 Township 17S	Range	30E	NMPM Eddy County	
10. Elevation	(Show whether DF, !			
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	3602'		<u> </u>	
11. Check Appropriate Box (o Indicate Nati	ire of Notice, R	Report, or Other Data	
NOTICE OF INTENTION TO:		SUE	SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABA	NDON RE	MEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	co	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING	C	CASING TEST AND CEMENT JOB		
OTHER:	🗆 o	THER: Intermed	iate casing & cement	
12 Describe Proposed or Completed Operations (Clearly state all pework) SEE RULE 1103. TD 4489'. Reached TD at 8:15 AM 11-(4493') of casing set at 4489'. Flower Commented with 1500 sacks Halliburton 2.03, weight 12.75). Tailed in with PD 8:42 PM 11-9-95. Bumped plug to Ran Temperature Survey and found to Spotted 200 sacks "C" and 2% CaCl2. Nippled up and tested to 5000#, OK. Reduced hole to 7-7/8". Resumed dr	9-95. Ran loat shoe set a Lite C, 10% a 200 sacks '1645 psi, OH of cement a PD 5:24 AM Drilled outling.	110 joints of at 4489'. If sack salt a 'C" and 2% Ca'C. Cement dis 1550'. Rai 11-10-95. Ot at 6:30 PM	8-5/8" 32# HC-80 and J-55 Float collar set at 4447'. and 1/4#/sack flocele (yield aCl2 (yield 1.32, weight 14.8). id not circulate. WOC 6 hours. a 1". Tagged cement at 440'. Circulate 15 sacks. WOC.	
I hereby certify that the information above is true and complete to the best of	f my knowledge and beli	ef.		
Kuster	mle	D J	Clerk pate11-13-95	
TYPEOR PRINT NAME Rusty Klein	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		505-748-1471 TELEPHONE NO.	
Tre Orranti Manual	IBØ		NOV 2 2 1005	

ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR

NOV 2 0 1995

__ DATE ---