

YATES PETROLEUM CORPORATION
Cedro APG State Com #1
Section 36-T17S-R30E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7730-7756' (Bone Springs): TIMES: TO 30"; SI 60"; TO 60"; SI 120". RECOVERY:
150' of drilling mud. SAMPLER: 2600 cc mud. PRESSURES: IHP 3576; IFP 29-57;
ISIP 144; FFP 58-72; FSIP 144; FHP 3576

DST #2 7990-8087' (Bone Springs): TIMES: TO 30"; SI 60"; TO 60"; SI 120". RECOVERY:
339' of oil and 1078' of water. SAMPLER: .59 cfg, 400 cc oil and 2260 cc water.
PRESSURES: IHP 3738; IFP 240-452; ISIP 1423; FFP 528-713; FSIP 2502; FHP 3743

DST #3 8268-8359' (Bone Springs): Misrun

DST #4 10850-10881' (Atoka): TIMES: TO 30"; SI 60"; TO 60"; SI 180". RECOVERY:
388' of oil and 420' of rathole mud. SAMPLER: 3.32 cfg, 300 cc oil and 200 cc mud.
PRESSURES: IHP 5210; IFP 408-441; ISIP 3014; FFP 278-408; FSIP 2835; FHP 5049

DST #5 10980-11015' (Atoka): TIMES: TO 30"; SI 60"; TO 60"; SI 180". RECOVERY:
101' of mud. SAMPLER: .47 cfg, 1200 cc mud. PRESSURES: IHP 5217; IFP 137-153;
ISIP 2457; FFP 117-153; FSIP 2957; FHP 5141

DST #6 11360-11438' (Morrow): TIMES: TO 30"; SI 60"; TO 60"; SI 180". RECOVERY:
187' of mud. SAMPLER: .59 cfg & 600 cc mud. PRESSURES: IHP 5414; IFP 101-114;
ISIP 1836; FFP 48-91; FSIP 3065; FHP 1584