

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-015-28760
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Dorothy 36 State Com
8. Well No. 1
9. Pool name or Wildcat Empire Morrow South
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3674' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator ARCO Permian
3. Address of Operator P.O. Box 1089 Eunice, NM 88231
4. Well Location Unit Letter <u>N</u> : <u>1163</u> Feet From The <u>S</u> Line and <u>1647</u> Feet From The <u>W</u> Line Section <u>36</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3674' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Casing Leak</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 11070' PBD: 10988' PERFS: 10780-10787'

01/03/99: MIRU Swab Unit. POOH w/plunger. RIH w/sinker bars to 9040'. Could not get SN.

01/07/99: MIRUPU. Unable to unset pkr.

01/08/99: RU wireline. RIH to check free point. Could not get tool in hole. POOH. RIH w/1-1/2" tool free point @ 9020'.

01/09/99: RIH cut tbg @ 9020'. POOH w/tbg.

01/10/99: RIH w/gauge ring & junk basket @ 7200'. POOH. Csg shows to be collapsed or hole starting @ 7200'. SI well. Engineering Evaluation Pending.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 02/08/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY Mike S. Well TITLE Field Rep. II DATE 3-12-99

CONDITIONS OF APPROVAL, IF ANY: