Form 3160-5 (November 1983) (Formerly 9-331)

UNITE STATES **DEPARTMENT OF THE INTERIOR**

SUBMIT IN TRIPLICATE *

(Other Instructions on reverse side)

| BUREAU | JOF LAND MANAGEMENT | 1; | Antesia in M 88210 | |
|---|---|--|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals.) | | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| OIL GAS WELL WELL | OTHER | 70531-123456 | 7. UNIT AGREEMENT NAME Skelly Unit | |
| 2. NAME OF OPERATOR The Wiser Oil Company | | 100 A 00 A | 8. WELL NAME AND NO. | |
| 3. ADDRESS OF OPERATOR | | 0 | 201 | |
| P.O. Box 2568 Hobbs, New Mexico 88241 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. ARTE See also space 17 below.) | | | 9. API WELL NO. 30-015-28947 | |
| LOCATION OF WELL (Report location See also space 17 below.) At surface | on clearly and in accordance with any Sta | tic requirements ARTESIA | 10. FIELD AND POOL, OR WILDCAT Grayburg Jackson Seven Rivers | |
| 1272' FSL & 45' FWL Unit M | | (See 81 (7 days) | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14-T17S-R31E | |
| 14. PERMIT NO | 15. ELEVATIONS (Show whether DF 3882' | | 12. COUNTY OR PARISH 13. STATE Eddy County NM | |
| 16. Check | Appropriate Box to indicate Nati | ure of Notice, Report, or Othe | er Data | |
| NOTICE OF INTENTION TO: | | | BSEQUENT REPORT OF: | |
| TEST WATER SHUT OFF | PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING WELL | |
| FRACTURE TREAT | MULTIPLE COMPLETE | FRACTURE TREATMENT | ALTERING CASING | |
| SHOOT OR ACIDIZE | ABANDON* | SHOOTING OR ACIDIZING | ABANDONMENT * | |
| REPAIR WELL | CHANGE PLANS | (Other) Re-perf. & acid | | |
| (Other) | | Completion or Recom | f multiple completion on Well pletion Report and Log form.) | |
| | drilled, give subsurface locations and mea ds & pump. ND WH. RU BOP. POH w/ | rtinent details, and give pertinent dates asured and true vertical depths for all n | is, including estimated date of starting any markers and zones pertinent to this work.) bit & 2-7/8" tbg. to 3645'. Could not drill thru | |
| 3/02/01 Computalog perf. San Andres f/3264 SPF. RD WL. Tested in hole w/2-7/ clean. Spotted 400 gals. Toluene. Se | ',68',74',3332'-34',3439'-40',60'-62',64' '8" x 5-1/2" Arrowset pkr. & 2-7/8" tbg. to et pkr. Pumped standing valve w/500# on | o 3859'. POH to 3300'. Hughes acid tbg. | Three Fingers f/3798',99',3801',02',03',13'-15' w/4 lized w/200 gals. 15% NE-FE acid. Circulated hole | |
| pkr. @ 3200'. Acidized Vac. 3264'- | 1890#. 15 min. 1800#. SI 1 hr. 1680#. | POH w/2-7/8" tbg. & pkr. RIH w/RE 1000# rock salt. Best block 300#. Be | MTP 3500# @ 4 bpm. Flushed w/27 bbls. fresh water. BP & pkr. on 2-7/8" tbg. Set RBP @ 3550'. POH & se sst break 200#. ATP 2200# @ 4 bpm. MTP 2570# @ | |
| 3/06/01 RIH & picked up RBP. POH w/2-7/8" tbg. LD 2-7/8" x 5-1/2 RBP & pkr. RIH w/2-16' pump. Left well pumping to SU Battery "A". | | IH w/2-7/8" tbg. Tbg. @ 3859'. SN | @ 3828'. RD BOP. NU WH. RIH w/rods & 1-1/2" x | • |
| | • | ACCEPTED FOR RE | CORD | |
| 18. I hereby certify that the foregoing is true a | nd correct. | | | |
| SIGNED Mary Jo Turny | TITLE Production Te | ОСТ 1 2001 • h II | DATE July 5, 2001 | |
| (This space for Federal or State office use) | | ALEXIS C. SWOBOD | MUJ | = |
| APPROVED BY | TUT C | PETROLEUM ENGINE | | |
| CONDITIONS OF APPROVAL IF ANY | TITLE | | DATE | |

EOLLO MEYLOU EVIOLO DE VELLES

388 8EU 5/2 VII 10: 7/2

BECENED