

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE Bureau No. 1004-0135

(Other Instructions on reverse side) Project No. 31, 1985

1501 W. Grand Avenue
Artesia, NM 88210
N.M. DIV-Dist. 2
Cons.
c/sf

MINAS REGISTRATION AND SERIAL NO.
LC-029418-A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

7. UNIT AGREEMENT NAME
Skelly Unit

2. NAME OF OPERATOR
The Wiser Oil Company

8. WELL NAME AND NO.
202

3. ADDRESS OF OPERATOR
P.O. Box 2568 Hobbs, New Mexico 88240

9. APINO.
30-015-29062

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1409' FSL & 1310' FWL
Unit L

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson 7-Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 14-T17S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3900'

12. COUNTY OR PARISH
Eddy County

13. STATE
NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☒
(Other) Acid

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

3/12/00 MIRU Tyler Well Service. POH w/rods. Parted 119th rod. RIH w/fishing tool & caught fish. Could not pull pump. Backed off at lift sub. POH w/rods. ND WH. RU BOP. Swab tbg. down. POH w/2-7/8" tbg. LD blast jt & BHA.

3/13/00 RIH w/2-7/8" tbg. Tbg. @ 3922'. SN @ 3890'. TAC @ 3296'. RD BOP. NU WH. RU Hughes Well Service. Pump 500 gals. 15% HCL anti-sludge acid w/50 gals. toluene. Spot across perf. 3365'-3866'. Let soak 1 hr. Pump 55 bbls. KCL down csg. to flush. RD Hughes. RIH w/rods & 2-1/2" x 1-3/4" x 16' pump. Left well pumping to Skelly Unit Battery "A". RDMO.

ACCEPTED FOR RECORD

JAN 23 2002

ALEXIS C. SVOBODA
PETROLEUM ENGINEER

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turvey TITLE Production Tech II DATE December 20, 2001

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Accepted for record

On Reverse Side

JAN 30 2002

RECEIVED
2002 JUN 18 AM 8:49
BUREAU OF LAND MANAGEMENT
FEDERAL GOVERNMENT