

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE Budget Bureau No. 1004-0135  
(Other Instructions on reverse side) Expire August 31, 1985

CLSF

RECEIVED  
1991 JUN -5 A  
BUREAU OF LAND MANAGEMENT  
SUNDARY NOTICES AND REPORTS ON WELLS  
LC-029418-B

SUNDARY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR The Wiser Oil Company		7. UNIT AGREEMENT NAME Moskelly Unit	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		8. API WELL NO. 30-015-29224	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 35' FSL & 1285' FWL Sec. 23-T17S-R31E Unit M		9. WELL NO. 267	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3838'		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23-T17S-R31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

ACCEPTED FOR RECORD  
JUN 05 1997

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>

(Other) Perforate, Acidize & Frac

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

01/03/97 Halliburton perforated San Andres Upper Jackson/Vacuum f/3662'-66', 77', 3738', 39', 40', 3806', 07', 08', 24', 25' & 26' w/1 SPF (15 holes).

01/06/97 Halliburton acidized San Andres Upper Jackson/Vacuum f/3662'-3826' w/2400 gals. 15% NE-FE acid & 30 ball sealers. Formation broke @ 2591#. Balled out w/13 bbls. in formation. MTP 4724# @ 6.4 bpm. ATP 3575# @ 4.4 bpm. ISIP 2274#. 5 min. 2036#. 10 min. 1980#. 15 min. 1970#.

01/08/97 Halliburton perforated Grayburg f/3520', 21', 22', 56', 62'-65', 73', 74', 84', 3617', 18', 19', 32' & 33' w/1 SPF (16 holes). Acidized perfs. w/2400 gals. 15% NE-FE acid & 32 ball sealers. Formation broke @ 2780#. Good ball action. MTP 3593# @ 6.3 bpm. ATP 3260# @ 4.8 bpm. ISIP 1965#. 5 min. 1879#. 10 min. 1866#. 15 min. 1858#.

01/10/97 Halliburton frac'd Grayburg/Vacuum perfs. 3520'-3677' w/12,000 gals. gelled water, 40,000 gals. Delta Frac #20 & 100,000# 16/30 sand. MTP 2922# @ 47 bpm. ATP 2743# @ 46 bpm. ISIP 2143#. 5 min. 2030#. 10 min. 2001#. 15 min. 1998#.

02/05/97 Ran 2-7/8" tbg. to 3842'. SN @ 3813'. TAC @ 3487'. Ran 2-1/2" x 2" x 16' RHTC pump.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Completion Department DATE March 3, 1997

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instruction On Reverse Side