

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Co. s.
N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210
APPROVED
Bureau No. 1004-0135
Expires: March 31, 1993

C15F

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☐ OIL WELL ☐ GAS WELL ☒ OTHER Tank Battery

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No. PO BOX 3109, MIDLAND, TEXAS 79701 397-0444

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter C : 990 Feet From The NORTH Line and 1650 Feet From The
WEST Line Section 11 Township 17-S Range 31-E

5. Lease Designation and Serial No.
LC-029418B

6. If Indian, Alottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
TEXMACK 11 FEDERAL

9. API Well No.

30-015-29720
FREN MORROW

11. County or Parish, State
EDDY, NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> OTHER: Request for variance
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true verticle depths for all markers and zones pertinent to this work.)

Texaco is giving notification of request of variance 004.III.D.4.(2) for the Texmack -11- Federal CTB lact unit. The meter has been repaired. After two provings, the base meter factor will be established as 1.0107 and the 1% unity will be based on this number for future factors. History of the meter indicates this would be a normal operating range.

If you have any questions, please feel free to call:

Homa Ray Short, FMT leader, (505) 887-5676
Bobby Hill, Engineer Assistant, (505) 394-1855



RECEIVED
2001 AUG 29 AM 10 54
BUREAU OF LAND MGMT.
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct:
SIGNATURE Bobby J. Hill TITLE Engineering Assistant DATE 8/29/01
TYPE OR PRINT NAME Bobby J. Hill
(This space for Federal or State office use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: