




Sheet No.

Anchor Test Daily Log Sheet

Tank Rental
&
Anchor Service
Corp.

DATE	COMPANY	LEASE & WELL NO.	ANCHOR LOCATION	PULL PRESSURE LBS.	SEAL #	TEST O.K.	PULLED UP INCHES	EYE BROKE	ROD BROKE	UNABLE TO LOCATE	UNABLE TO TEST	SUCKER ROD PIPE CABLE	MARKER	REMARKS
11/24/97	Shoh-Ara Oil Co.	Benson "f" #20	SE	18600	130805	✓								new new Anchor
			SW	4	130806	✓							4	"
			NW	4	130807	✓							4	"
			NE	4	130808	✓							4	"
ART		PATTERN 10059	GERONIMO											
			SE											
			SW											
			NW											
			NE											
ART		PATTERN	GERONIMO											
			SE											
			SW											
			NW											
			NE											
ART		PATTERN	GERONIMO											
			SE											
			SW											
			NW											
			NE											
ART		PATTERN	GERONIMO											
			SE											
			SW											
			NW											
			NE											
ART		PATTERN	GERONIMO											
			SE											
			SW											
			NW											
			NE											
ART		PATTERN	GERONIMO											

ART - ANCHOR REPLACEMENT TEST