



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **067136**
Unit **Scout-Federal**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT (Temporary)	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 10, 1958

Well No. **Scout Federal #12310** is located **2310** ft. from **N** line and **1650** ft. from **E** line of sec. **34**
SE/4, SW/4, NE/4 **18-S 25 E** **N.M.P.M.**
Wildcat (Sec. and Sec. No.) **Eddy** (Twp.) (Range) (Meridian)
New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3494** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-12-58 to 7-18-58 Drilled Bridge Plugs
7-20-58 to 7-22-58 Squeezed perms. from 1214-1406 with 50 sxs Portland cement.
7-22-58 to 9-1-58 Drilled to 2800'. Installed tubing head and temporarily abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Yates Brothers**
Address **309 Carper Building**
Artesia, New Mexico

M. E. Spitzer
By **M. E. Spitzer**
Title **Geologist**

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11

11/11/11