

34. 11

Company	R. W. Fair				
Farm Name	Falkenberg			Well No.	1
Land Classification	Patented				
Sec.	24	Twp.	18	Range	26 County Eddy
Feet from Line:	2310	N.		S.	E. 990 W.
Elevation	2000			Method	
Contractor					Scout
Spudded	Completed			Initial Production	
Bond Status					

ACID RECORD

Gals.TATSBS

TRS

TBL

TWL

Top Pay

TD

SHOOTING RECORD

No. of Quarts

Shot at

FeetNo. of Quarts

Shot at

Feet

S/O [illegible]

S/O 5

S/O

S/O

S/O

S/O

[illegible]

LOG

[illegible]

NEW XICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Artesia, New Mexico

Place

8/20/41

Date

OIL CONSERVATION COMMISSION,
 Santa Fe, New Mexico

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

R. W. Fair (owner)

Company or Operator

Falkenberg

Lease

Well No. 1

in the

SW-NW 1/4

of Sec. 24

T. 18

, R. 26

, N. M. P. M.,

Dayton

Field, Eddy

County

The dates of this work were as follows: 8-13-14-15th, 1941

Notice of intention to do the work was (was not) submitted on Form C-102 on yes 8/12 19 41
 and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Hole ~~was~~ filled with mud to 1240 ft. and put in 22 sacks of cement. Then filled with mud and rock to 890 ft. Put in 22 sacks of cement after driving plug in end of 8 1/4 casing filled with mud to cellar and cemented marker.

Witnessed by _____

Name

Company

Title

Subscribed and sworn to before me this 20th

day of August, 19 41

W. B. Byers

Notary Public

I hereby swear or affirm that the information given above is true and correct.

Name D. J. Truett

Position agent

Representing R. W. Fair

Company or Operator

My Commission expires 9/25/44

Address Tyler, Texas

Remarks:

Ray Yarborough

Name

Oil & Gas Inspector

Title