


KIMBLE OIL CO. C TEXAS

B&B Federal # 1-C 330/N + 1980/W 36-18-26

DAYTON ABO



8 5/8" - 24# @ 990 w/600SY

Work over to be done

1. Need to R.U. + Check for hole in Csg - Run bond log on 5 1/2"
2. if hole is found seg and test.
3. Pump RA pill down 8 5/8" if pass shoe brader head seg surface.

5 1/2" - 14#C 6388 w/300SY

no Records of well problems
no indication of whether or not Cmt Csg on 8 5/8" Csg.
no Cmt top on 5 1/2"