

RECEIVED

NEW MEXICO DIVISION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Chevron Oil Company		8. Farm or Lease Name C. R. Martin
3. Address of Operator P. O. Box 1660 Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER J , 1650 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 18-S RANGE 26-E NMPM.		10. Field and Pool, or Wildcat Atoka (Penn)
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 6-15-72, 750 sacks class "C" cement with 2% calcium chloride were pumped down the 5 1/2" x 10 3/4" annulus. Maximum pressure 1200 psi. Final pressure with pumps shut down 325 psi. After waiting on cement 10 hours, a temperature survey indicated bottom of cement at 1950'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. S. Roberts TITLE Area Engineer DATE 6-19-72

APPROVED BY W. A. Gressett TITLE JLE AND GNS INSPECTION DATE JUN 21 1972

CONDITIONS OF APPROVAL, IF ANY: