

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

Corrected Report

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Martin Yates, III, 312 Carper Building, Artesia, N. Mex.
(Address)

LEASE Everest WELL NO. 2 UNIT L[✓] S 14 T 18S R 26E

DATE WORK PERFORMED 11-29-57 POOL Atoka

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Ran 1741.08 feet of new 5½", 14# casing and cemented with 450 sacks Pozmix, with 8 sacks Howcogel, which circulated cement to surface.

Waited on cement 48 hours and test showed water shut-off.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name M L Armstrong

Title OIL AND GAS INSPECTOR

Date DEC 9 1957

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Nola Carder

Position Bookkeeper

Company Martin Yates, III

OIL CONSERVATION COMMISSION
 ALBERTA DISTRICT OF
 REGISTRATION
 REGISTRATION