

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Martin Yates, III, 312 Carper Bldg., Artesia, N. Mex.
(Address)

LEASE Everest WELL NO. 2 UNIT L S 14 T 18 S R 26 E
DATE WORK PERFORMED 12-4-57 POOL Atoka

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Perforating and fracturing

Detailed account of work done, nature and quantity of materials used and results obtained.

Perforated 5½" casing from 1666 to 1674 with four shots per foot.
Sand-fractured well from 1666 to 1674 with 10,000 gallons heavy oil
and 10,000 pounds heavy sand, running 250 gallons MCA ahead of
fracturing treatment.

Test after treatment and recovering load oil showed production
of 100 barrels of oil and no water in 24 hours.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
		(Company)

OIL CONSERVATION COMMISSION

Name ML Armstrong
Title OIL AND GAS INSPECTOR
Date DEC 27 1957

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name Nola Carder
Position Bookkeeper
Company Martin Yates, III

OIL CONTAMINATION REPORT	
ALERT - OIL CONTAMINATION	
No. OILCO-100-1000	
Date: 10/10/10	
Time: 10:00	
Location: 1000	
Quantity: 1000	
Density: 1000	
Composition: 1000	
Test Method: 1000	
Remarks: 1000	
Signature: 1000	
Date: 10/10/10	