

June 17 Dug 3'X3'X4' deep pit

June 18 Rigged up pulling unit came out of hole with rods and pump. Released TAC pulled tubing out of hole. Ran back in with bailer cleaned from 3604.10 to 3759.31 POH with bailer emptied in pit shut in well shut down.

June 19 Ran bailer went down to 3852.31 POH BS & Iron sulfite cleaned out tool in pit. Ran back in to 3852.31 pulled back out with tool. Closed well in, shut down.

June 20 Ran in hole with tubing and set TAC 15 points nipples up wellhead ran in hole with pump and rods re-spaced and hung well on, rigged down

June 20 Called vacuum truck out to suck out 3.5 BBL fluid hauled to disposal

July 1 Cleaned location with backhoe picked up all trash covered 3'X3'X 4' deep pit

