

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		Abandonment of well	<input checked="" type="checkbox"/>

Artesia, New Mexico

July 16, 1942

Place

Date

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____
Brainard & Guy B-9299 Well No. 1 in the _____

Company or Operator

Lease

NWNE NE

of Sec. 12

T. 18

R. 27

N. M. P. M.,

Artesia

Field,

Eddy

County.

The dates of this work were as follows:

Completed July 14, 1942.

Notice of intention to do the work was (was not) submitted on Form C-102 on SG 106 2 -17-42 19

and approval of the proposed plan was (~~was not~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Please refer to my report of February 17, 1942.

Run 15 sacks cement in bottom of hole and tested for water
in one week. No water.

Filled with mud to 450.

Run 5 sacks cement at 450 which was inside the 8 5/8 casing

Filled with mud to top.

Set marker on two sacks cement.

Pulled 270 ft. of 8 5/8 casing. Left 187 feet in hole from 270

to 457.

Witnessed by _____ Brainard & Guy, Fred Brainard, Partner _____
Name Company Title

Subscribed and sworn before me this 16 _____

I hereby swear or affirm that the information given above
is true and correct.

_____ day of July, 1942, 19 _____

Name Fred Brainard (Signed) _____

Position Partner _____

George Nixon (Signed) _____

Notary Public

Representing Brainard & Guy _____
Company or Operator

My commission expires Oct. 3, 1944 _____

Address Artesia, New Mexico _____

Remarks:

Roy Yarbrough (Signed) _____

Name

Oil & Gas Inspector _____

Title