

DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-5313	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Gulf Oil Corporation ✓		8. Farm or Lease Name Eddy I State (NCT-A)	
3. Address of Operator Box 670, Hobbs, New Mexico 88240		9. Well No. 1	
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 18-S RANGE 27-E NMPM.		10. Field and Pool, or Wildcat Empire Abo	
15. Elevation (Show whether DF, RT, GR, etc.) 3519' GL		12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6063' PB.

Pumped 1000 gallons of 15% NE acid down tubing over 5-1/2" casings perforations 5862' to 5918'. Flushed and over flushed with 35 barrels of oil. Maximum pressure 1800#, ISIP 100#, after 1 minute on vacuum. AIR 3.5 BPM. Swabbed and cleaned up and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>K. J. Breazale</u>	TITLE <u>Area Engineer</u>	DATE <u>February 9, 1973</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>FEB 14 1973</u>

CONDITIONS OF APPROVAL, IF ANY: