

Form 1001
MAY 1963

N. M. O. C. C. COEN

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.
LC-065478(B)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ WELL ☒ GAS ☐ WELL ☐ OTHER ☐
2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION
3. ADDRESS OF OPERATOR
BOX 68, HOES, N. M. 85240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980 FNL x 660 FEL Sec 3 (Unit H. SE 1/4 NE 1/4)
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, CF, etc.)
3574' R DB

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
MALCO H. Federal R/AC
9. WELL NO.
2
10. FIELD AND POOL, OR WILDCAT
EMPIRE Abo
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
3-18-27 NM PM
12. COUNTY OR PARISH
EDDY
13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☒
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In an effort to increase productivity remedial work performed as follows:

Repair tubing leak and acidized perfs
5650-70' w/ 2000 gal 15%. Evaluated and
restored to production.

Pre-Flow 105 BO + 0 BW 24 hrs. BOE 1019.
After Flow 367 BO + 0 BW 24 hrs. BOE 980.

TD-6123
P2D-6090
5/2" CSA 6123

OC-6-11-70
COMP 6-16-70

RECEIVED
JUN 29 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO
D. C. C.
ARTESIA, OREILE

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE AREA SUPERINTENDENT DATE JUN 26 1970

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:
032-6695-ART
1- HCS
1- SSSP
1- ATANTR
JUN 29 1970
Date
ACCEPTED FOR RECORD PURPOSES
ACTING District Engineer
See Instructions on Reverse Side