


(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. **LC 070937**

Unit _____



UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

7-26-62, 19

Federal 'EG' /
Well No. **1** is located **1592** ft. from **N** line and **2302** ft. from **E** line of sec. **4**
NE SW 4 **18-6** **27-4** **N M P M**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Unmanned **Lddy** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3597** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per requested by phone this well has been plugged as follows:

Pulled tubing and left 4-1/2" casing in hole.

20 sk. plug set from 2920 to 2820

5 sk. plug set from surface and marker.

Heavy mud spotted between plugs

RECEIVED

SEP 12 1962

O. C. C.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Hondo Oil & Gas Company**Address **Box 129****Artesia, New Mexico**By *A. H. Brown*
Title **Dist. Prod. Supt.**