


Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office **Las Cruces**
Lease No. **060894**
Unit **1**

Copy to 57



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Test

Return to production

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Graridge Corporation
Paton Federal is located **1650** ft. from **N** line and **2310** ft. from **W** line of sec. **6**
Well No. **1**
NE/4 SE/4 NW/4 **18 P. S.** **28 S.** **RMPM Meridian**
Red Lake **Eddy** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3424** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran Tubing and rods, tested well.

Results of 24 hr. pumping test. 5 bbls. Oil 3 bbls. Water

RECEIVED
MAR 20 1964
U. S. GEOLOGICAL SURVEY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Graridge Corporation**

Address **Drawer B**
Artesia, N.M.

By *J. H. Arnall*
Title **Dist. Supt.**