

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instr. is on re-  
verse side)Copy 6  
Form approved.  
Budget Bureau No. 42-R1424

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME West Red Lake Unit
2. NAME OF OPERATOR Atlantic Richfield Company		8. FARM OR LEASE NAME West Red Lake Unit
3. ADDRESS OF OPERATOR P.O. Box 1978, Roswell, New Mexico 88201		9. WELL NO. 8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FEL (Unit Letter G)		10. FIELD AND POOL, OR WILDCAT Red Lake-Gryburg, SA
14. PERMIT NO.		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 7, T18S, R27E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3367' DF		12. COUNTY OR PARISH Eddy
		13. STATE N.M.

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Add Perforations

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MI & RU plg unit 3/11/70. Perforated 1084-88, 1094-98 w/2 JSPF. Treated perms 1084-1098 w/750 gallons 15% HCl LSTNE acid and ball sealers and 12,000# 20/40 sand in 12,000 gallons slick fresh water. Reran production tubing string and rods and pump as pulled and returned well to production. Work completed 3/15/70.

RECEIVED

MAR 20 1970

O. C. C.  
ARTESIA, OFFICE

RECEIVED

MAR 19 1970

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*D. D. Hutchins*

TITLE

Dist. Drlg. Supervisor

DATE

3/18/70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES

MAR 19 1970  
Date

ACTING

*J. B. Baker*  
District Engineer

\*See Instructions on Reverse Side