

ARTESIA OFFICE COPY
(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 026855-A

Unit Vandagriff

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 26, 1944, 19

Well No. #1 is located 630 ft. from [N] line and 660 ft. from [W] line of sec. 8

NW NW Sec. 8
(1/4 Sec. and Sec. No.)

18S
(Twp.)

27E
(Range)

N.M.P.M.
(Meridian)

Artesia
(Field)

Eddy
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 1144' of 7" casing and cemented with 100 sacks. Shut down 72 hours to test cement. Work done by Halliburton.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company David C. Saikin et al

Address Artesia, New Mexico

By *David C. Saikin*
MH

Title Operator