



ARTESIA OFFICE COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
P. O. Box 187
Artesia, New Mexico

November 8, 1951


Mr. Julian E. Simon
c/o William Hudson
Artesia, New Mexico

Re: Oil & Gas Lease
L. C. 054205

Dear Sir:

Your "Subsequent Report of Abandonment" dated November 6, 1951, covering your No. 4 Compton well, located on the subject land in the NE¹/₄, NE¹/₄, section 8, T. 18S., R. 27E., Red Lake Field, Eddy County, New Mexico is hereby approved.

Very truly yours,


John A. Frost
District Engineer.

JAF:mnn
Inspected by John A. Frost
November 6, 1951

Form 9-331a
(March 1942)

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 054205
Unit A

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 6, 1951, 19

Compton
Well No. #4 is located 990 ft. from N line and 990 ft. from E line of sec. 8
SW 1/4 NE 1/4 NE 1/4 Section 8 18 South, 27 East N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
EMPIRE EDDY NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On August 28th, 1951 we ran 2" tubing to bottom of hole at 1227'; filled hole with mud, using 41 sacks and circulating to surface; spotted 10 sacks of cement on bottom to cover oil pay; shot off casing at 815' and recovered that much 7" casing; ran tubing to 125' and spotted 10 sacks of cement. Cemented required marker with 5 sacks and cleaned up location.

Work was done by Denton Cementing Company and the Lea County Casing Pullers.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company JULIAN E. SIMON
Address % William Hudson
Artesia Hotel Bldg.,
Artesia, New Mexico
By W. M. Hudson
Title Agent.