

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instructio.
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-070938

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Humble Oil & Refining Company

CHANGE OPERATOR NAME FROM
HUMBLE OIL & REFINING COMPANY
TO EXXON CORPORATION
EFFECTIVE JANUARY 1, 1973

3. ADDRESS OF OPERATOR

P.O. Box 2100, Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

660 ft. ~~N~~ of S Line and 1980 ft. ~~N~~ of W Line of Sec 9,
T-18-S, R-27-E, Eddy County, New Mexico

14. PERMIT NO.

-

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3508 D.F.

7. UNIT AGREEMENT NAME

Chalk Bluff Draw (A)

8. FARM OR LEASE NAME

--

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Empire Abo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 9 T-18-S, R-27-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pumping Unit Installed.

24 hr test produced 61 bbls oil plus 8 bbls water.
12 - 72" SPM.

RECEIVED

APR 21 1965

U. S. G.
ARTESIA OFFICERECEIVED
APR 19 1965
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

COPY ORIGINAL
SIGNED: E. S. DAVIS

TITLE

Dist. Adm. Supvr.

DATE

4-14-65

(This space for Federal or State office use)

APPROVED BY
CONDITION OF APPROVAL

APPROVED

APR 20 1965
RUDOLPH C. BAIER, JR.
ACTING DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
JAN 10 1964
U.S. AIR FORCE
HEADQUARTERS
WASHINGTON, D.C.

2000 2. 3 1964

100-100000-100000
100-100000-100000
100-100000-100000
100-100000-100000
100-100000-100000