



(SUBMIT IN TRIPPLICATE)

LAND OFFICE NM=031186

LEASE NO. Hondo Lease Unitized

UNIT

RECEIVED

MAR 24 1960

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUNDRY NOTICES AND REPORTS ON WELLS D. O. C. E.  
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING Casing
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTAL WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOT DATE OR OTHER DATA)

Duo-Chalk Bluff Draw Unit

March 24, 1960

1960

WELL NO. 6 IS LOCATED 990 FT FROM {N} LINE AND 110FT FROM {W} LINE OF SEC. 9  
{SW} TWP. 13-8 Range 6 Diana

NAME OF WELL	9	13-8	6 7-8	DIANA
(SEC. AND SEC. NO.)	(TWP.)	(RANGE)	(COUNTY)	(STATE OR TERRITORY)
Empire Abo Unassigned	Bddy		New Mexico	
(SEAL)	(COUNTY OF OBSERVATION)		(STATE OR TERRITORY)	

THE ELEVATION OF THE DERRICK FLOOR ABOVE SEA LEVEL IS 5240 FT.

## DETAILS OF WORK

STATE NAMES OF AND EXPECTED DEPTHS TO COLLECTIVE SANDS SHOW BGS, WEIGHS, AND VOLUMES OF PROPOSED CEMENTS; INDICATE MUDGING JOBS, CEMENTING POINTS, AND ALL OTHER REPORTS ON THIS WORK.

Set 5655.30' of  $4\frac{1}{2}$ " J-55 9.5# deg (178 ft) at 36°C. Cemented w/150 s/s regular 4# gel cement. POB 1:45 AM 3-20-60. Top of cmt 4100'. Comp Survey. Tested  $4\frac{1}{2}$ " csg w/1200' for 30 minutes = no drop in pressure. Ran Log.

I UNDERSTAND THAT THIS PLAN OF WORK MUST RECEIVE APPROVAL IN WRITING BY THE BUREAU SURVEY BUREAU BEFORE OPERATIONS MAY BE COMMENCED.

COMPANY: Humble Oil &amp; Refining Company

ADDRESS: Box 2347, Hobbs, N.M.

Title Agent

## OIL COMPANIES

*Franklin & Marshall*

—  
—

—  
—  
—  
—  
—

—  
—  
—

*W. C. Gandy, Jr., and J. W. Gandy, III*

## ANSWER