

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN DUPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-065478(b)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION ✓

3. ADDRESS OF OPERATOR

BOX 38, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

983.25 FSL x 2297.02 FEL Sec 9 (Unit O, SW/4SE/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3513' R. D. B.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MALCO "K" FEDERAL

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

EMPIRE Abo

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

9-18-27 NMPM

12. COUNTY OR PARISH 13. STATE

EDDY

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☒

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In an effort to reduce GOR propose remedial work as follows:

Squeeze perforations 5610-46 w/ 125 SX LWH Cement. WOC and clean out to PBD-5804'. Reperforate. @ 5676-87, 5696-5708, 5715-22, 5737-42, w/ deep penetrating charges. Evaluate and restore to production.

PROD TEST- 9-20-68 FLW 10680 x 0 BW 24 hr. GOR 4585'

TD- 5835'

PBD- 5804'

4 1/2" CSA 5835'

RECEIVED
OCT 7 1968
U. S. GEOLOGICAL SURVEY
CARROLL COUNTY, MISSISSIPPI
OCT 8 1968

18. I hereby certify that the foregoing is true and correct

SIGNED

AREA SUPERINTENDENT

TITLE

DATE OCT. 5, 1968

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

049- USGS- ART
1- NSD
1- SUSP
1- RPY
1- ATLANTIC

APPROVED
OCT 7 - 1968
R. L. GLENN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side