

(SUBMIT IN TRIPLICATE)

Land Office Las CrucesLease No. 065478(b)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYUnit W-1-V-5-1

COPY 1317

APPROVED
1962
A. L. ...
ACTING DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

USA Malco Refineries "D" COPY May 2, 1962

Well No. 3 is located 1980 ft. from [N] line and 1980 ft. from [E] line of sec. 10SW 1 sec. 10 18 S 27 E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Empire Abo Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In accordance with form 9-331A approved 4-13-62 the well was plugged and abandoned as follows:

Shot and pulled 5 1/2" casing from 5050' & set cement plugs as follows:

<u>SX</u>	<u>Interval</u>
20	5808-5700
25	5050-half in and half out of 5 1/2" stub
35	3550-3450
35	1770-1670
30	990-half in and half out of 9-5/8" stub
10	Surface.

All intervals filled with heavy mud laden fluid. Erected P&A marker. Subsequent report will be submitted upon completion of restoration of ground to its natural contour.

Company Pan American Petroleum Corp.Address Box 68Hobbs, New MexicoBy orig. /s/ by V. E. StaleyTitle Area Supt.