

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TR: DATE:
(Other instructio. on re-verse side)

Form approved.
Budget Bureau No. 43-71484.

5. LEASE IDENTIFICATION AND NUMBER

NM-025604

6. IF INDIAN, ALLOTTEE OR TRUST NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MALCO G. 7-1-1964

9. WELL NO.

9

10. FIELD AND POOL, OR WILDCAT

EMPIRE Abo

11. SEC., T., R., OR BLK. AND SURVEY OR AREA

(EMPIRE G6) 10-18-27

12. COUNTY OR PARISH

EDDY

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Amoco Production Company

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

1980 FSL x 660 FWL Sec. 10 (Unit L, NW 1/4 SW 1/4)

3474 R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER Casing ☐

FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐ ABANDON* ☐

REPAIR WELL ☐ CHANGE PLANS ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ RETAINING WELL ☐

FRACTURE TREATMENT ☐ ALTERING CASING ☐

SHOOTING OR ACIDIZING ☒ ABANDONMENT* ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sand-perforations to this work.)

Perforations 5795-5837 were acidized w/ 1500 gals of acid-solvent blend (80% acid-20% Solvent) and evaluated.

Prior - pmp 36 BO + 1 BW 24 hrs. GOR 5805.

after - pmp 107 BO + 2 BW 24 hrs. GOR 794.

TD-6032

PB-5840

4 1/2" CSA 6024

Perfs: 5795-5804

5815-17, 35-37

6024-32

OC - 5-8-72

COMP - 5-15-72

RECEIVED

MAY 19 1972

U.S. GEOLOGICAL SURVEY

ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE _____ DATE **MAY 17 1972**

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY

041- USGS- A

1- Div

1- Susp

1- Hondo

*See Instructions on Reverse Side