

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 067858

Unit _____

30-015-00866

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

USA MALCO REFIDARIES "B"April 22, 19 58Well No. 2 is located 660 ft. from N line and 660 ft. from W line of sec. 11NW/4 NW/4 Sec. 11 T-10-S R-27-E NM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Wildcat Edy New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is _____ ft. furnish later.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to drill the above well with rotary tools to an approximate depth of 6105 to test the Abo. Casing program will be as follows:

Size of Hole	Size of Casing	Depth	Cement
<u>11"</u>	<u>8-5/8"</u>	<u>960</u>	<u>Circulate 6% gel with 100 mx</u> <u>neat on bottom</u>
<u>7-3/4"</u>	<u>5-1/2"</u>	<u>6100</u>	<u>150 sacks neat</u>

ILLEGIBLE

I understand that this plan of work _____ are operations may be commenced.

Company Pan American Petroleum CorporationAddress Post Office Box 68Hobbs, New MexicoBy Ralph HendersonTitle Field Superintendent