



(SUBMIT IN TRIPLICATE)

 UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

 Land Office New Mexico
 Lease No. 03602
 Unit _____
RECEIVED

JUN 8 1960

SUNDRY NOTICES AND REPORTS ON WELLS
 O. C. C.

ARTESIA, OFFICE 2	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 100 ft. from N line and 600 ft. from E line of sec. 21
10 (Twp.) 27 (Range) 1 (Meridian)
11 (Field) 280 (County or Subdivision) New Mexico (State or Territory)

 The elevation of the derrick floor above sea level is 570 ft.
DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled hole to 1470' and ran 1470' of 7 1/2" casing, setting in to
 cement water control. Failed to offset derrick then core cemented with
 mud. Failed to cement 25 hours, drilled plug and applied to 1470'.
 Failed to set, failed to set and ran boiler measuring no fluid.
 Failed ahead.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

 Company 100 mile building
 Address 100 mile building

 By Donald G. Stuenkel
 Title _____