1	
NO. OF COPIES RECEIVED 24	
	Form C-103
	SEIVED Supersedes Old
SANTA FE I NEW MEXICO OIL CONSERVATI	ION COMMISSION C-102 and C-103 Effective 1-1-65
FILE I V	
	20 1975 5a. Indicate Type of Lease
LAND OFFICE	State 🚺 Fee
OPERATOR 2	5. State Oil & Gas Lease No.
ARTE	BIA OFFICE B - 10568
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSAL	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSI	DIFFERENT RESERVOIR.
	7. Unit Agreement Name
OIL GAS WELL OTHER-	Artesia State Unit
2. Name of Operator	8. Farm or Lease Name
Anadarko Production Company	Tract No. 9
3. Address of Operator	9. Well No.
P. O. Box 67, Loco Hills, New Mexico 88255	9. Well NO.
4. Location of Well	
UNIT LETTER A 330 FEET FROM THE North	10. Field and Pool, or Wildcat
UNIT LETTER A 330 FEET FROM THE North LINE A	ND 990 FEET FROM Artesia
THE East 188	
THE East LINE, SECTION 23 TOWNSHIP 188 RAI	NGENMPM.
15. Elevation (Show whether DF, RT, (
<u>1111111111111111111111111111111111111</u>	Eddy
Check Appropriate Box To Indicate Nature of	f Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
_	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA	
TEMPORARILY ABANDON	
	EST AND CEMENT JOB
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and g work) SEE RULE 1103. 	ive pertinent dates, including estimated date of starting any proposed
1. GO International logged OH easter these	
1. GO International logged 7" casing shoe @	· 1750' •
2. Pumped 100 sx cement plug @ 1907'.	
3. Shut in 17 hours; wait on cement; tagged	l top of plug @ 1470'.
4. Circulated hole with mud.	
5. Shot 7" casing @ 1435'; could not pull.	
6. Spotted 35 sx cement plug from 1470' to 1370'.	
7. Shot 7" casing @ 1001'; could not pull casing.	
8. Spotted 35 sx cement plug from 1050' to 950'.	
 4. Circulated hole with mud. 5. Shot 7" casing @ 1435'; could not pull. 6. Spotted 35 sx cement plug from 1470' to 7. Shot 7" casing @ 1001'; could not pull c 8. Spotted 35 sx cement plug from 1050' to 9. Shot 7" casing @ 500'; could not pull casing @	
9. Shot 7" casing @ 500'; could not pull ca 10. Shot 7" casing @ 400'; pulled 13 joints	sing.
	of 7" casing.
11. Spotted 35 sx cement plug from 500' to 3	,50°•
12. Pumped 10 sx cement plug @ surface.	
13. Erected dry hole marker, closed pits and	cleaned location on 8-4-75.
	and the second
	14710 - 12
	7.
	•
. I hereby certify that the information above is true and complete to the best of my knowle	edge and belief.
Original Signed by	
	pervisor October 13, 1975
	pervisor DATE October 13, 1975
$f' p \subseteq$	
OIL AND GAL	
PROVED BY Jerre Durgellonne TITLE OIL AND GA	S INSPECTOR OCT 2 2 1975
PROVED BY J.C. CTILL CLER CONDITIONS OF APPROVAL, IF AND:	DATE OCT 2 2 1975