

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-7

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - 17 (FORM C-101) FOR SUCH PROPOSALS.

|                                                                                                                                                                                                        |                                                  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                                                  | 7. Unit Agreement Name                           |
| 2. Name of Operator<br>Yates Drilling Company                                                                                                                                                          | 8. Firm or Lease Name<br>Artesia Metex Unit      |
| 3. Address of Operator<br>207 S. 4th, Artesia, N.M. 88210                                                                                                                                              | 9. Well No.<br>#9                                |
| 4. Location of Well<br>UNIT LETTER <u>I</u> , <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>18</u> RANGE <u>27</u> N.M.P.M. | 10. Field and Pool, or Wildcat<br><u>Artesia</u> |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br><u>2575</u>                                                                                                                                           | 12. County<br>Eddy                               |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

|                                                |                                                                            |
|------------------------------------------------|----------------------------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>                                  |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                                      |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <u>Test, run casing, produce</u> <input checked="" type="checkbox"/> |

### SUBSEQUENT REPORT OF:

|                                                     |                                               |
|-----------------------------------------------------|-----------------------------------------------|
| REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> |                                               |
| OTHER <input type="checkbox"/>                      |                                               |

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE HOLE 1103.

This well was plugged as follows: 25 sack cement plug placed in bottom of well through pay section, mudded to bottom of 8 5/8" casing. 10 sack cement plug placed in pipe, 278' of 8 5/8" pipe recovered from 480' originally run. Well mudded to surface and regulation marker set. We are concerned that the subject well needs to be re-entered and checked for waterflood response and possible loss of water out of the pay zones.

We propose to re-enter to pump test the well under open-hole conditions. Based on pump test, run casing and produce well or replug.

12' H<sub>2</sub>O @ 375  
8 5/8" @ 480' w/ 35 Sxs.

0-45' caliche  
45-330 Red Beds  
330-1440 anhy  
1440-1470 Red sd.  
1470-1675 sdy ls.  
1675-1686 "

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. J. P. Jones TITLE Production Supervisor

1687-1715 sdy ls Blv. sh.  
1715-1765 anhy  
1765-1797 anhy & ls.  
DATE 10-12-83

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

1797-2010 Gray ls.  
2010-2035 sdy ls  
2035-2095 ls  
0.1 sh. @ 2000