

# NEW MEXICO OIL CONSERVATION COMMISSION

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	REPORT ON PROGRESS	<b>X</b>

September 6, 1951      Artesia, New Mexico

Date

Place

Following is a report on the work done and the results obtained under the heading noted above at the

Malco Hesler Yates      State      Well No. 114  
 NE SE      Company or Operator      Lease      189      27E      in the  
 of Sec. 25      T.      R.      N. M. P. M.,  
 Artesia      Pool      Eddy      County.

The dates of this work were as follows:

Completed on August 30, 1951

Notice of intention to do the work was (XXXX) submitted on Form C-102 on various dated 19 51  
 and approval of the proposed plan was (XXXX) obtained. (Cross out incorrect words)

### DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

This well drilled to 6014'. Now shut down, waiting on heavier drilling equipment.

Witnessed by \_\_\_\_\_ Name \_\_\_\_\_ Company \_\_\_\_\_ Title \_\_\_\_\_

APPROVED:  
 OIL CONSERVATION COMMISSION

*Just E. Kenna*  
 Name  
 OIL AND GAS INSPECTOR  
 Title

SEP 10 1951

Date

I hereby swear or affirm that the information given above is true and correct

Name *Vilas P. Sheldon*  
 Vilas P. Sheldon,  
 Position Secretary, Operating Committee  
 Representing Malco Hesler Yates  
 Company or Operator  
 Address Carper Building, Artesia,  
 New Mexico.