

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	/
U.S.G.S.	/
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

AUG 29 1980

O. C. D.

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Artesia Metex Unit
9. Well No. 1 #56
10. Field and Pool, or Wildcat Artesia Grbg. SA
12. County Eddy

SUNDY NOTICES AND REPORTS ON WELLS, ARTESIA, OFFICE  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
Yates Drilling Company

3. Address of Operator  
207 So. 4th Street, Artesia, NM 88210

4. Location of Well  
UNIT LETTER A 330 FEET FROM THE North LINE AND 330 FEET FROM  
THE East LINE, SECTION 35 TOWNSHIP 18S RANGE 27E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3548 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Bradenhead Test</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug out well head 5½ casing on clamps on top of surface pipe. Installed 1" pipe between 5½" and surface pipe. Grouted in with cement. One inch valve above ground and level - shut in 24 hours before inspection. No pressure on surface pipes or casing. Tubing pressure 1150. Inspected by Mr. Weaver, OCD, Artesia.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. W. Weaver TITLE Drilling Supervisor DATE August 28, 1980

APPROVED BY B. W. Weaver TITLE OIL AND GAS INSPECTOR DATE SEP 8 - 1980

CONDITIONS OF APPROVAL, IF ANY: