

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	1
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL AND GAS COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 29 1980

O. C. D.

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		ARTESIA OFFICE	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Yates Drilling Company		8. Farm or Lease Name Artesia Metex Unit	
3. Address of Operator 207 So. 4th Street, Artesia, NM 88210		9. Well No. 1 #58	
4. Location of Well UNIT LETTER C 330 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 18S RANGE 27E NMPM.		10. Field and Pool, or Wildcat Artesia Grbg. SA	
15. Elevation (Show whether DF, RT, GR, etc.) 3548 GR		12. County Eddy	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Bradenhead Test

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug out bradenhead Installed 2" high pressure valve. Swidged down with tapped ball plug to 1/2" needle valve above ground level. Bradenhead and casing shut in 24 hours before inspection. No pressure on bradenhead or casing. Tubing pressure 1150. Inspected by Mr. Weaver, OCD, Artesia.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Brian Davis TITLE Drilling Supervisor DATE August 28, 1980

APPROVED BY B. W. Weaver TITLE OIL AND GAS INSPECTOR DATE SEP 8 - 1980

CONDITIONS OF APPROVAL, IF ANY: