

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Donnelly Drilling Co., Inc., Box 433, Artesia, New Mexico
(Address)

LEASE State A WELL NO. 3 UNIT EV S 2 T 18S R 28E

DATE WORK PERFORMED July 18, 1959 POOL Artesia

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

After cleaning out ahead of and driving 8 5/8" casing, it was finally landed at 477'. The string of pipe was pulled apart at top joint in effort to pick it up off bottom. It appears that the only way to free it would be by pump pressure which could cause pipe to either be bumped out of hole or apart down the hole. For that reason, we drilled out of pipe, bailed hole dry and are drilling ahead in a dry hole. Pipe landed January 18, 1959.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test _____

Oil Production, bbls. per day _____

Gas Production, Mcf per day _____

Water Production, bbls. per day _____

Gas-Oil Ratio, cu. ft. per bbl. _____

Gas Well Potential, Mcf per day _____

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name M L Armstrong

Name W Donnelly

Title _____

Position President

Date _____

Company Donnelly Drilling Co., Inc.