

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY OLEN F. FEATHERSTONE, c/o Juanita Denton, Box 308, Artesia, N.Mex.
(Address)

LEASE Featherstone-State WELL NO. 7 UNIT M S 2 T 18S R 28E
DATE WORK PERFORMED 3/16/56 POOL Artesia

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Ran 2626 feet of 5-1/2" - 14 pound new casing and cemented with
100 sacks cement. Float collar and Texas Pattern shoe. (Denton Oil
Well Cementing Company).

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name

Title

Date

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name

Position

Company

Agent

OLEN F. FEATHERSTONE

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

February 15, 1956 Artesia, New Mexico
(Date) (Place)

Following is a report on the work done and the results obtained under the heading noted above at the

OLEN F. FEATHERSTONE

(Company or Operator)

Featherstone-State (B-7071)

(Lease)

Kersey & Company

(Contractor)

Well No. 7 in the SW 1/4 SW 1/4 of Sec. 2

T. 18S, R. 28E, NMPM, Artesia Pool, Eddy County.

The Dates of this work were as follows: February 8, 1956

Notice of intention to do the work (was) (was not) submitted on Form C-102 on _____, 19____,

(Cross out incorrect words)

and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Ran 546' of 32# 8-5/8" New Casing and cemented with 50 sacks cement.

Texas Pattern Shoe. Tested complete water shut-off.

Witnessed by Harold Kersey Kersey & Company Contractor
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

H. A. Johnson
(Name)

(Title)

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name *Juanita Denton*

Position Agent

Representing Olen F. Featherstone

Address c/o Juanita Denton, Box 308,
Artesia, New Mexico