


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **026772 (b)**
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	XX
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 3, 19 **58**

Well No. **Dunn No. 27** is located **1900** ft. from **N** line and **640** ft. from **E** line of sec. **12**
NE/4 SE/4 Sec. 12 **18 S** **28 E** **NM PM**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Artesia Pool **Eddy** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3622** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to total depth of 2867'. At that depth ran 2867' of 4 1/2" O.D.
9.5 lb./ft. new seamless casing and cemented with 200 sacks. Ran
Gamma-Ray Neutron Survey to total depth and tested pipe with 1000 lb.
prior to perforating. Pipe tested O.K. Will perforate and frac 4 zones.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Western - Yates**

Address **P. O. Box 427**

Artesia, New Mexico

RECEIVED APR 5 1958
By **W B Macey**
Title **Chairman of Operating Committee**

