

STATE N.M.	COUNTY Sherman	ELEVATION	DESC. BY Sharon	COMPANY Franklin, Cotes & Fair
KIND OF SAMPLES	LOCATION	S 14	T 18	R 28
		FARM Stab 14	WELL NO. 6	

DEPTH	DOLO		LIME	DESCRIPTION	SALT		ANHY	SHALE				SAND			CHT	NOTES
	%	%			%	%		RED	GRY.	GRN.	BLK.	RED	GRY.	DESCRIPTION		
2081-92						90						10				
2091-97						80						20				
2097-02												100		lightly eroded		
2103-15						90						10				
2115-25						90						10				
2125-30						10						90				
2130-43						80						20				
2143-49						90						10				
2149-65						90						20	10	gray sd. is oil stained		
2165-81												100				
2181-91	90			buff f.s.								10				
2192-02	80			" " "		10						10				
2202-11	95			light sb f.s.								5				
2211-23	90			" " "								10				
2223-54	100			buff f.s.												
2235-75	95			" " "				5	maroon							
2245-85	100			" " "												
2285-00	95			" " "								5				
2300-07	100			" " "												
2307-20	80			pink sandy												
2320-25	90			buff f.s.								30				
2325-35	90			pink sandy								10				
2335-42	100			light sb f.s.												
2342-40	90			white i.s.												
2348-55	95			" " "				5	maroon							
2355-23	90			" " "				5								
2373-83	100			light buff f.s.												
2383-94	40			" " "										60 many sandy, no staining		
2391-09	95			" " "								5				
2409-25	100			" " "												
2425-33	90			light gray sandy												

1000 2 1000 2 1000 2 1000 2

1000 2 1000 2

1000 2 1000 2

1000 2 1000 2

1000 2 1000 2

1000 2 1000 2

1000 2 1000 2