

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

May 10, 1954

(Date)

Artesia, New Mexico

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Malco Resler Yates

(Company or Operator)

State

(Lease)

S. P. Yates Drilling Company

(Contractor)

Well No. 118 in the NW 1/4 SW 1/4 of Sec. 14

T. 18, R. 28, NMPM, Artesia Pool, Eddy County.

The Dates of this work were as follows: May 6th and 7th

Notice of intention to do the work (was) (was not) submitted on Form C-102 on \_\_\_\_\_, 19\_\_\_\_\_,  
(Cross out incorrect words)

and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Drilled well to 2564'. Encountered oil shos at 2237-50' and from 2509-16'.  
Set 7" casing at 2425' and cemented w/100 sax. Hole was reduced to 6 1/4" at  
2425'. Will sandfrac and complete in accordance with C-102 of May 10th.

Witnessed by \_\_\_\_\_  
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

H. A. Johnson  
(Name)

(Title) (Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: Dallas P. Shelton

Position: Sec. Oper. Comm.

Representing: Malco Resler Yates

Address: 314 Carper Bldg., Artesia, N.M.