							- 1				
SANTA FE	PIES RECEIVED	· · · · · · · · · · · · · · · · · · ·	•	NEW MEX		CONSER	, VATION	COMMISSIO	N	FORM C-103	
U.S.G.S. LAND OFFICE TRANSPORTER	LAND OFFICE					(Rev 3-55)					
PRORATION OF			(Subn	nit to approp	priate Distr	ict Office	as per Cu	mmission Rule	1106/	1 ²²	
Name of Company Address Western-Yates P.O. Box 427, Artesia, New Mexico										exico	
		ant		Well No. 123	Unit Lette J	r Section 14	Township	1 ∦- S	Range	28-E	
	Date Work Performed 6-25-62 Pool Artesia						County Eddy				
THIS IS A REPORT OF: (Check appropriate block)											
Beginni	ng Drilling C)perations	C	asing Test a	nd Cemen. Ju	ob (X Other (-			
	Plugging Remedial Work					conversion of well to Injection.					
The State 647 No. 123 was converted to a water injection well June 25, 1962. Injection is through tubing under a packer set at 2340' into perforations at 2350-56' and open hole interval from 2451-2573'.											
RECEIVLD										VLD	
JUL 1 2 1962										1962	
Name changed from D. D. C. C. WESTERN-YATES to INTERNATIONAL TATES Sfrective December 31, 1963											
Witnessed by R. J. Davenport				Position Prod	Position Prod. Supt.			Company Western-Yates			
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA											
DF Elev.			PBTD				Producing Interval		Comp	Completion Date	
Tubing Diame		Tubi	ng Depth		Oil Sr.	ing Diame	ter	Oil String	g Depth		
Perforated Int	erval(s)										
Open Hole Interval Producing Formation(s)											
RESULTS OF WORKOVER											
Test Before	Date o Test		il Production BPD		Production CFPD	Water P B	roduction PD	GOR Cubic feet/B	ы	Gas Well Potential MCFPD	
Workover											
Workover	N					,					
						I hereby certify that the information given above is true and complete to the best of my knowledge.					
Approved by MLarmstrong						Name Blanciport					
en are els inspector						Production Superintendent					
Date						Company Western-Yates					