- Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-015-01869	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088 :::::::::::::::::::::::::::::::::::	5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	0. C. D.		6. State Oil & Gas Lease No. State 647	
( DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	CES AND REPORTS ON WEL POSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PEF -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL GAS WELL XX WELL		I SI WELL DUCTION.		
2. Name of Operator YATES PETROLEUM CORPOR	ATION 🗸		8. Well No. 124	
3. Address of Operator 105 South 4th St., Art	esia, NM 88210		9. Pool name or Wildcat Artesia-Q-G-SA	
NOTICE OF IN PERFORM REMEDIAL WORK	18S Rame   10. Elevation (Show whether Indicate Inditer Indicate Inditer Indicate Inditer Inditer Inditer Ind	28E DF, RKB, RT, GR, etc.) Nature of Notice, R SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: RETURN W	SEQUENT REPORT OF:	
Pull tubing. Run Bullo bad casing at 87'. I Screw into collar. In paraffin. Ran tubing	dog bailer on tubing to Pull casing and lay down Istalled new 5½x2-3/8 La to TD with abrasive jet Day @ 2610'). Swab well	clean out fill n. Ran 87' of n arkin K wellhead tool. Pump 50	ubing and tag bottom at 2611'. . Clean out to 2620'. Found new 5-1/2" 14# casing. d. LD tubing and steam out DO gals 15% acid on perfs wab clean. Run rods and pump.	

- / -/	nation above is true and complete to the best of my knowledge $a$	md belief. mn.e Production Supervisor	9-15-92
TYPE OR PRINT NAME	Juanita Goodlett		<b>ТЕLЕРНОНЕ НО.</b> 505/748-1471
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILL LAMS		SEP 1 8 1992
APPROVED BY	SUPERVISOR, DISTRICT IN	TILE	DATE